



Office of Laboratory Licensure, Certification and Training
Bureau of State Laboratory Services

250 N. 17th Avenue
 Phoenix, AZ 85007
 602-364-0720
 FAX 602-364-0759

A list of director approved analytes available to all laboratories. This list is current as of **June 2005**.

Director Approved Methods (Refer to A.A.C. R9-14-610.A for references.) AIR = Air program.
 SDW = Drinking water. WW = Wastewater. HW = Solid, Liquid, and Hazardous Waste.
The following compounds have been added as a target analytes for the referenced method.

Compounds	Internal Code	Reference	Method
2, 4 – dinitrotoluene 2, 6 – dinitrotoluene 4, 4' – DDE Acetochlor EPTC Molinate Terbacil	SDW	D3	525.2
4, 4' – DDE	SDW	D3	508
4, 4' – DDE	SDW	D3	508.1
DCPA di acid degradate DCPA mono acid degradate	SDW	D	515.1
DCPA di acid degradate DCPA mono acid degradate	SDW	D3	515.2
EPTC Molinate Terbacil	SDW	D3	507
Polychlorinated Biphenyls as Aroclors	SDW	D3	508.1
MTBE	SDW	D3	502.2
MTBE Nitrobenzene	SDW	D3	524.2
Acetophenone Alpha-terpineol Aniline Carbazole o-Cresol n-Decane 2,3-Dichloroaniline n-Octadecane Pyridine p-Cresol	WW	E	625
PETN	HW	F	8332