

CORF  
TOP NINE FEDERAL DEFICIENCIES  
(01-01-15 through 12-31-15)

485.62(b)	Sanitary Environment
485.58	Comprehensive Rehabilitation Program
485.58(a)(1)	Physician Services
485.58(b)(4)	Plan of Treatment
485.62	Physical Environment
485.62(a)(3)	Safety and Comfort of Patients
485.62(b)(3)	Sanitary Environment
485.62(c)(1)	Maintenance
485.64(b)(1)	Drills and Staff Training

**0579:**

The facility must maintain a sanitary environment and establish a program to identify, investigate, prevent, and control the cause of patient infections.

**0532:**

The facility must provide a coordinated rehabilitation program that includes, at a minimum, physicians' services, physical therapy services and social or psychological services. The services must be furnished by personnel that meet the qualifications set forth in §485.70 and must be consistent with the plan of treatment and the results of comprehensive patient assessments.

**0533:**

A facility physician must be present in the facility for a sufficient time to--

- Provide, in accordance with accepted principles of medical practice, medical direction, medical care services and consultation;
- Establish the plan of treatment in cases where a plan has not been established by the referring physician;
- Assist in establishing and implementing the facility's patient care policies; and
- Participate in plan of treatment reviews, patient case review conferences, comprehensive patient assessments and reassessments and utilization reviews.

**0539:**

The plan of treatment must be reviewed at least every 60 days by a facility physician who, when appropriate, consults with the professional personnel providing services. The results of this review must be communicated to the patient's referring physician for concurrence before treatment is continued or discontinued

**0570:**

The facility must provide a physical environment that protects the health and safety of patients, personnel, and the public.

**0574:**

A fire alarm system with local (in-house) capability must be functional, and where power is generated by electricity, an alternate power source with automatic triggering must be present.

**0582:**

The facility must make available at all times a quantity of laundered linen adequate for proper care and comfort of patients. Linens must be handled, stored, and processed in such a manner that prevents the spread of infection.

**0585:**

The facility must establish a written preventive maintenance program to ensure that all equipment is properly maintained and equipment needing periodic calibration is calibrated consistent with the manufacturer's recommendations.

**0600:**

The facility must provide ongoing training and drills for all personnel associated with the facility in all aspects of disaster preparedness.